



TEST REPORT

Report No.: THSH20123028661EN

Job No.:28661

Date: January 06, 2021

Applicant : Gemcreate Electronics Technology (Shanghai) CO., LTD
Floor 3-1,Building 1,Jiaotong University Science Park, NO.1599 Fengpu Avenue,
Feng Xian District, Shanghai 201499, P.R. China

Sample Description : Transmitter instrument housing

Sample Material : 316 stainless steel

Date Received : December 30, 2020

Test Period : December 30, 2020---January 06, 2021

Test Requested : IP67

Test Method : IEC 60529:1989+A1:1999+A2:2013

Conclusion : Pass

Authorized Signature



For and on behalf of

Shanghai Global Testing Services Co., Ltd.

Shi Lei/Kevin

General Manager -GTS/SHO

Page 1 of 4

This report is only responsible for the tested sample(s) from the client, the testing result(s) is used for scientific research, teaching or internal quality control. Without the writing agreement of the company, the client is not allowed to copy the report in part(entire copy is excepted).

Shanghai Global Testing Services Co., Ltd.

Floor 2nd, Building D-1, No. 128, Shenfu Road, Minhang District, Shanghai, China.

Tel: (86-21) 3363 7866 Fax: (86-21) 3363 7858 E-mail: info@gts-lab.com Web Site: <http://www.gts-lab.com>

TEST REPORT

Report No.: THSH20123028661EN

Job No.:28661

Date: January 06, 2021

SAMPLE PHOTO



TEST RESULT

No.	Test Item	Test Method	Result
1	IP6X	IEC 60529:1989+A1:1999+A2:2013	PASS
2	IPX7	IEC 60529:1989+A1:1999+A2:2013	PASS



TEST REPORT

Report No.: THSH20123028661EN

Job No.:28661

Date: January 06, 2021

1. Test Item: IP6X Dust proof

Test Method: IEC 60529:1989+A1:1999+A2:2013 Degrees of protection provided by enclosures (IP 6X)

Test setup: Dust-proof chamber, Model No. SC-010

Environment: 24°C, 53%RH, 103kPa

Test Conditions: 1) Maximum depression : 2kPa.
2) Test period: 8 hours
3) Extraction rate: 40 volumes per hour

Test Result:

Sample Name	Test Results
Transmitter instrument housing	No dust observed inside the test sample

Sample Photo(s) during the test:



Sample Photo(s) after the test:



TEST REPORT

Report No.: THSH20123028661EN

Job No.:28661

Date: January 06, 2021

2. Test Item: IPX7 Water proof

Test Method: IEC 60529:1989+A1:1999+A2:2013 Degrees of protection provided by enclosures (IP X7)

Test setup: Water proof test chamber, Model No. IPX1-8

Environment: 26°C, 53%RH, 103.5kPa

Test Conditions: 1) Depth of water: 1m
2) Test period: 30 min

Test Result:

Sample Name	Test Results
Transmitter instrument housing	No Water entered the cavity of sample after this test

Sample Photo(s) during the test:



Sample Photo(s) after the test:



*****End of Report*****